

Re: Kinder Morgan

Kimberly McEathron to: Manuel Nolau

Kimberly McEathron/R2/USEPA/US From:

To: "Manuel Nolau" < Manuel. Nolau@dep.state.nj.us>

Great. Thanks for all the information Manny. Take care.

Kim

~*~*~*~*~*~*~*~*~*

Kimberly McEathron Water Compliance Branch Division of Enforcement and Compliance Assistance **USEPA Region 2** 290 Broadway, Floor 20 New York, NY 10007 ph: (212) 637-4228

fax: (212) 637-4211

McEathron.Kimberly@epa.gov

"Manuel Nolau" Good afternoon Kimberly: Please see attached. ... 11/16/2011 03:59:10 PM

11/16/2011 04:00 PM

From: "Manuel Nolau" < Manuel. Nolau@dep.state.nj.us> Kimberly McEathron/R2/USEPA/US@EPA To:

Date: 11/16/2011 03:59 PM

Subject: Kinder Morgan

Good afternoon Kimberly:

Please see attached. The facility is not complying with the General Stormwater Permit. It is impossible. Even if the piles are covered, during loading and unloading the piles have to be uncovered. From past experience all the piles in that area were uncovered during winter time. Once the permit is issued, I am assuming that a certain amount of time will be given to Kinder Morgan to come into compliance. I have not issued any penalties to Kinder Morgan. Kinder Morgan surrounded one of the storage areas with a berm. The berm is supposed to hold a 10 year storm. I have not pushed berms on the other piles because I do not know the final conditions of the individual permit. The individual permit will address the salt, and Belgian piles, and the maintenance area. Kinder Morgan is in the process of moving the maintenance area into a building with three bays.

Take care and have fun tomorrow

Manuel Nolau, Environmental Engineer New Jersey Department of Environmental Protection Northern Bureau of Water Compliance and Enforcement 7 Ridgedale Avenue Cedar Knolls, NJ 07927

[attachment "NOV sent with letter dated 3-17-2008.pdf" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "Cover letter dated 3-17-2008.pdf" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "IMG 3312.JPG" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "IMG_3313.JPG" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "IMG 3314.JPG" deleted by Kimberly

McEathron/R2/USEPA/US] [attachment "IMG_3315.JPG" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "IMG_3316.JPG" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "Inspection report sent with letter dated 3-17-2008.pdf" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "NJ0117838 - Administrative completeness.pdf" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "NJ0117838 - Authorization page.pdf" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "NJ0117838 - Draft Cover Letter.pdf" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "NJ0117838 - Fact Sheet.pdf" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "NJ0117838 - Part i.pdf" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "NJ0117838 - Part ii.pdf" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "NJ0117838 - Part iii.pdf" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "NJ0117838 - Part iv.pdf" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "NJ0117838 - Part iv.pdf" deleted by Kimberly McEathron/R2/USEPA/US] [attachment "NJ0117838 - Table of Contents.pdf" deleted by Kimberly McEathron/R2/USEPA/US]